

# Oil Field Environmental Incident Summary

**Incident:** 20141104185440

**Date/Time of Notice:** 11/04/2014 18:54

**Responsible Party:** Big Lease Trucking LLC

**Well Operator:**

**Well Name:**

**Field Name:**

**Well File #:**

**Date Incident:** 11/1/2014

**Time Incident:** 03:20

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 156

**Rng:** 96

**Sec:** 8

**Qtr:** N2 NW

**Location Description:** Tidal Energy Marketing Group Terminal (Suncor 60th Street NW Williams County Tioga ND 58552  
Suncor is a Facility (Lact) for unloading crude oil trucks.

**Submitted By:** Lamont Black

**Received By:**

**Contact Person:** Lamont Black  
Box 1035  
Killdeer, ND 58640

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 2 Mile

**Distance Nearest Water Well:** 2 Mile

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	10	Gallons				

Brine

Other

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

none

**Areal Extent:**

10x25 feet

**Potential Environmental Impacts:**

none

**Action Taken or Planned:**

Check parking brakes on trucks, make sure brakes are properly adjust and set the parking brake on the trailer, double chock wheels and position truck so it isn't on such a steep decline. hold saftey meeting with the drivers review unloading procedures.

**Wastes Disposal Location:** Clean Harbors

**Agencies Involved:**

**Updates**

---

**Date:** 11/5/2014    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill impacted the surrounding area at a location that is not associated with E & P. Followup is necessary.

---

**Date:** 3/30/2015    **Status:** Inspection

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

3/30/2015 at 18:09, on location. Truck loading/unloading station has a few scattered stains smaller than 1 ft X 1 ft, but the 10 X 25 stain in the report appears to have been cleaned up.